SILVERSTAR MOTORCARS 19717 VALLEY BLVD WALNUT, CA. 91789

TERMINAL I.D.:

0075420008018488984000

MERCHANT #:

8018488984

MASTERCARD ***********2353

SALE RECORD #: 1 DATE: AUG 03, 12 BATCH: 601

000001 THU: TIME: 10:16 091502

AUTH:

TOTAL \$1125.54

JASON YOUNG

I AGREE TO PAY ABOVE TOTAL AMOUNT ACCORDING TO CARD ISSUER AGREEMENT (MERCHANT AGREEMENT IF CREDIT VOUCHER)

CUSTOMER COPY

£ ARD00257154

ENDOR.

9-

19717 Valley Blvd. Walnut CA, 91789

> TEL (909) 612-7398 FAX (909) 612-7396

www.wihasilverstar.com

Invoice #0007776 Original Estimate #0011769

Date: 8/3/12

Page: Page 1 of 1 Advisor: HANK

Print Time # 10:39:49AM

Vehicle: 2011 PORS 911

License: 6RFU593

VIN: WP0CD2A95CS773114

Engine:

Mileage: 3736

CLR: BLACK

Trans: AUTO

Labor

42.88

PROD: 05/11

Price

61.12

15.00

Parts Subtotal

76.12 119.00

Part Description

CHANGE SERVICE, CHANGE OIL UP TO SIX QUARTS, REPLACE OIL HASSIS, CHECK/FILL GEARBOX FLUID, CHECK/FILL WASHER FLUID, FLUID, CHECK/FILL BATTERY FLUID, CHECK FILL TRANSMISSION

FLUID, CHECK AIR FILTER, INSPECTED WIPER BLADES, CHECK

TIRE PRESSURE, ROTATE TIRES.

MOBIL 1 SYN 0W40 OIL MOBIL 1 SYN 0W40 OIL 8.50 1.00

POR 11 TUR OIL FIL WIX 57694

BRK005 001BRAKE INSPECTION -

FRON BRAKE PADS : 90% REAR BRAKE PADS : 90%

Includes - Road test vehicle, check brake rotors, pads and shoe thickness and

brake drum diameter. Inspect brake hydraulic system.

0010NBOARD COMPUTER ANALYSIS **DIA015**

001SILVERSTAR COMPLEMENTARY CAR WASH! THANKS FOR YOUR BUSINESS. MAR006

0.00

0.00

0.00

AUG 03 2017

All labor charges are fixed prices and bear no relationship to actual hours of labor performed. All references herein or otherwise including any posting of labor rates or flat labor hours are for information only to indicate to the customer the basis upon which the fixed prices were established, but neither such references or posting nor the fact that the actual hours of labor performed may be more or less than the indicated flat rate hours shall have any effect whatsoever on the fixed prices so charged. All parts are new or factory rebuilt unless specified otherwise. Customer acknowledges recipt of goods and/or service in the amount of the total shown heron and authorizes us to process credit card voucher, if any, in customers name. Warranty is 12 months 12,000 MILES.

SIGNATURE X

I acknowledge notice and oral approval of an increase in the original estimated price.

(signature or initials)

Labor: \$42.88 \$76.12 Parts: \$0.00 Sublet: \$0.00 Other Fees: 1.19 hazard waste \$120.19 Subtotal: \$6.66 Sales Tax: Paid By: MSTR CHARG Total: \$126.85 Paid: \$126.85 Pay Ref:

Due:

\$0.00





3425 North Digitial Drive • Lehi, UT 84043 Telephone: (801) 852-5440

0213I4PCS269930

Customer Number 56	67875	Advisor YAVITED KAR	WEDE	0510	Tag Number		L: 801-390-9
		XAVIER KAB		6513	8254	04/21/21	4PCS269930
		Voer A A-L- a A-L-	License Number	Milea	23,210	Polor	Stock Number -
		12/PORSCHE	/911/2DR	CAB TU	RB0	Delivery Date	Delivery Mles
		W P O C D	2 A 9 5 C	S 7 7	3 1 1 4	Selling Dealer Number	Production Date
		ET.E. Number		P.O. Numb	er	RO04/13/21	
OD# 1 CHARGES-		Comments					MO: 232
ABOR							
# 1 20AUZ@210 PERF COMF	PORSCHE MINOR SEF FORM PORSCHE MINOR SEF PLETED MAJOR SERVICE	RV. TECH(S) RVICE	:6912		1300.00		
	FP-NUMBER						
1 8 1	0PB-115-403 110539 900-123-106-30	OIL FILTER BULK OW40 MOBIL ALUM SEAL RING	TOTAL -	7 PRICE- 38.61 7.75 1.78 PARTS	38.61 62.00 1.78 102.39		Jr
DB# 1 TOTALS							
			LABOR		1300 00		

[CONTINUED ON NEXT PAGE]

06:34pm

PARTSQTYFP-NUMBER 1	OIL FILTER BULK OW40 MOBIL ALUM SEAL RING	UNIT PRICE- 38.61 7.75 1.78 TOTAL - PARTS	1 70
JOB# 1 TOTALS			-02.05
		LABOR PARTS	1300.00 102.39
JOB# 2 CHARGES	JOB# 1 JOURNAL PREFIX 4P0	CS JOB# 1 TOTAL	1402.39
LADOD			
PERFORM VEHICLE COND PERFORM VEHICLE INSPE COMPLETED SENT VIDEO	REPORT TECH(S):69 CTION AND REPORT	912	0.00
PARTSQTYFP-NUMBER 1 9A1-102-216-01 1 997-110-131-30	DESCRIPTION		
1 9A1-102-216-01	SYNCHRO*5 FILTER *5 CABIN-AIR FILTER TRNSMSSN OIL - P TRANS OIL PAN	OC OC	06.06
1 997-110-131-30	FILTER *5		96.06
1 997-571-219-01	CABIN-AIR FILTER	71.19 83 31	71.19 83.31
6 000-043-305-13	TRNSMSSN OIL - P	83.31 37.83 399.34	226.98
1 9G1-321-025-00	TRANS OIL PAN	399.34	399.34
13 9G1-321-801-00	TRNSMSSN OIL - P TRANS OIL PAN TORX-HEAD SCREW SPARK PLUG PORSCHE BRAKE FLUID BRAKE FLUID HEXAGON FLANGE N	2.40	31.20
6 999-170-229-00	CDADK DILIC		ara bear a comment and
1 PKBRAKE	DODCCHE BRAKE FLUTS	24.54	147.24
1 000-043-210-82	D RDAKE ELLITO	***	****
1 PAF-007-634	HEXAGON FLANCE N	38.94	38.94
	TEXAGON TEANGE N	10.78	10.78
7004 2 707112		TOTAL - PARTS	1105.04
JOB# 2 TOTALS			
		PARTS	1105.04
JOB# 3 CHARGES	JOB# 2 JOURNAL PREFIX 4PC	S JOB# 2 TOTAL	1105.04
LABOR			
J# 3+03AUZ070 REPLACE 4 TIRE	C TECHTON		
Added Operation (42KORBING @ 04/13 REPLACE 4 TIRES	/2021 17:11)	12	70.00
BOTH REAR TIRES BALD O AND BALANCED WHEELS. T	N INNER EDGE. REPLACED TIRES, CL EST DROVE VEHICLE AND SET TPMS.	EANED	
PARTSQTYFP-NUMBER	DESCRIPTION		
2 1-015-300	302/30/10		
HANK VENT V12 EV	VO2 102Y	284.81	569.62

CUSTOMER COPY

PAGE 1 OF 3





3425 North Digitial Drive • Lehi, UT 84043 Telephone: (801) 852-5440

0213I4PCS269930

Seller hereby expressly disclaims all warranties, either expressed or li chantability or fitness for a particular purpose, and neither assumes n ly in connection with this sale.			6513	3 Tag 8254	04/21/21	4PCS26	9930
567875	XAVIER KA	License Num			Color	Stock Number	
engan a packay					Delivery Date	Delivery Miles	
	2/PORSCH				Selling Dealer Number	Production Da	ate
	P O C [2 A 9		7 3 1 1 4			Service of the servic
	E. Number		P.O. N.	lumber.	04/13/21		7.0
	mments					MO:	23
			TAL - PARTS				· Suga
CODEDESCRIPTION		CONTROL	NO	4.00	-		
							- 1911
TT TIRE TAX			TAL - MISC	0.00			できた。
				70.00			417 24 - 42
# 3 TOTALS		LA P.	ABOR ARTS	70.00 569.62			
			ISC	8.00			
	JOB# 3 JOURNAL PREFI	rx 4PCS JC	OB# 3 TOTA	AL 647.62			- 2
	70R# > >001/11/1-						
# 4 CHARGES							
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCER	RN TECH	H(S):6912					
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCER	RN TECH	H(S):6912					
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI	H(S):6912 RE DIM THAN					
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCEF Ided Operation (42XAVIERK @ 04/20/202: CUSTOMER STATES PASSENGER STHE DRIVER'S SIDE. PLEASE	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE.	H(S):6912 RE DIM THAN	i.				
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED	H(S):6912 RE DIM THAN LED HOUSING	i.				7
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCER ded Operation (42XAVIERK @ 04/20/202:	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED	H(S):6912 RE DIM THAN LED HOUSING	i.				7
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCER ided Operation (42XAVIERK @ 04/20/202: CUSTOMER STATES PASSENGER : THE DRIVER'S SIDE. PLEASE (RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED	H(S):6912 RE DIM THAN LED HOUSING	i.				7
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCEF ded Operation (42XAVIERK @ 04/20/202:	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME		0.00			Ay Company
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME		0.00			A. Company of the Com
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME		0.00			4. Company of the com
B# 4 CHARGES BOR 4+30AUZ010 INT/EXTERIOR CONCER ded Operation (42XAVIERK @ 04/20/202:	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME	JOB# 4 TOT	0.00	<u>o</u>		As a second seco
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME	JOB# 4 TOT	0.00 TAL 0.00	<u>o</u>		Z. Carlotte Company
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912	J. N ER JOB# 4 TOT	0.00 TAL 0.00	<u>o</u>		NA NA STATE OF THE
B# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912	J. N ER JOB# 4 TOT	0.00 TAL 0.00	<u>o</u>		T.
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F IAL COUPLING FLUID. P	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 CH(S):6912 CH(S):6912	J	735.00	<u>o</u>		T The state of the
B# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F IAL COUPLING FLUID. P ESTER AND TOPPED UP F	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 TLTER. ALSO ERFORMED :UID.	J	735.00	0		The second secon
B# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F IAL COUPLING FLUID. P	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 CHITER. ALSO DERFORMED CHUID.	J	735.00	0		No.
BB# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 ILTER. ALSO ERFORMED LUID.	JOB# 4 TOT	735.00 RICE- 68.47 136.9 ARTS 136.9	0		7
BB# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 ILTER. ALSO ERFORMED LUID.	JOB# 4 TOT JOB# 4 TOT O TOTAL - PA	735.00 RICE- 68.47 136.9 ARTS 136.9	0 - 0 94 94		No.
BB# 4 CHARGES	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 221 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 CH(S):6912	JOB# 4 TOT JOB# 4 TOT O TOTAL - PA LABOR PARTS	735.00 RICE- 68.47 136.9 ARTS 136.9	0 0 94 94 00 94		44
BB# 4 CHARGES 4+30AUZ010 INT/EXTERIOR CONCER ded Operation (42XAVIERK @ 04/20/202:	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 TLTER. ALSO PERFORMED LUID.	JOB# 4 TOT UNIT PR 6 TOTAL - PA LABOR PARTS	735.00 RICE- 68.47 136.9 ARTS 136.9	0 0 94 94 00 94		T.
BB# 4 CHARGES 4+30AUZ010 INT/EXTERIOR CONCER ded Operation (42XAVIERK @ 04/20/202:	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 TLTER. ALSO PERFORMED LUID.	JOB# 4 TOT UNIT PR 6 TOTAL - PA LABOR PARTS	735.00 RICE- 68.47 136.9 ARTS 136.9	0 0 94 94 00 94		*
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED.THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 221 17:51) PLACED OIL PAN WITH F LAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON JOB# 5 JOURNAL PR	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 CH(S):6912 CHUID.	JOB# 5 TO	735.00 RICE- 68.47 136.9 ARTS 136.9	0 - 0 94 94 94 94		T)
B# 4 CHARGES BOR	RN TECH 1 09:45) SIDE TAIL LAMP IS MOI CHECK AND ADVISE. TIONS AND INSPECTED ING AS DESIGNED. THERE END REMOVING TINT TO JOB# 4 JOURNAL PREF 121 17:51) PLACED OIL PAN WITH F IAL COUPLING FLUID. P ESTER AND TOPPED UP F TRNSMSN OIL FRON JOB# 5 JOURNAL PR AG T	H(S):6912 RE DIM THAN LED HOUSING IS TINT ON FIX CUSTOME FIX 4PCS CH(S):6912 TLTER. ALSO PERFORMED LUID.	JOB# 5 TO	735.00 RICE- 68.47 136.9 ARTS 136.9 735.0	0 - 0 94 94 94 94		*






3425 North Digitial Drive • Lehi, UT 84043 Telephone: (801) 852-5440


DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The Seller hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any

CELL: 801-390-925 ag N8254 4PCS269930 04/21/21 6513 567875 XAVIER KABWERE 23,210 2/PORSCHE/911/2DR CAB TURBO P 0 C D 2 A 9 5 C S 7 7 3 1 1 4 04/13/21 MO: 23218 367.50 LABOR JOB# 6 JOURNAL PREFIX 4PCS JOB# 6 TOTAL 367.50 DOB# 7 CHARGES-----LABOR------219 95 TECH(S):6912 PORSCHE 4WHEEL ALIGN J# 7+07AUZ010 Added Operation (42KORBING @ 04/21/2021 16:45) COMPLETED ALIGNMENT DOB# 7 TOTALS-----219.95 LABOR JOB# 7 JOURNAL PREFIX 4PCS JOB# 7 TOTAL 219.95 MISC-----CODE------DESCRIPTION-----42.56 SS SHOP SUPPLIES JOB # A 42.56 TOTAL - MISC ESTIMATE-----CUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$4987.00 (+TAX) 2692.45 TOTAL LABOR.... **************** 1913.99 TOTAL PARTS.... 0.00 TOTAL SUBLET...] [] CASH [] CHECK CK NO. [0.00 TOTAL G.O.G.... 50.56 TOTAL MISC CHG. [] MASTERCARD [] DISCOVER [] VISA 0.00 TOTAL MISC DISC TOTAL TAX..... 332.69 [] CHARGE [] OTHER [] AMER XPRESS 4989.69 **TOTAL INVOICE \$** THANK YOU FOR YOUR BUSINESS!! CUSTOMER SIGNATURE

olds Company CC657793 Q (08/13)

Porsche: 911 Turbo: 2007-13 Carrera (997): except GT2 4-Wheel Total Alignment





Multi-Point Inspection

Date/Time: 04/21/2021 18:34:26 Vehicle Year/Model: 12 PORSCHE 911 Customer Name: MATTHEW H MACKAY Odometer: 23210 VIN: WP0CD2A95CS773114 Phone: (H) (801) 619-2108 Tag: 8254 RO: 269930 Technician: KORBIN T GOLDER Service Advisor: XAVIER KABWERE REQUIRES IMMEDIATE ATTENTION WILL REQUIRE FURTHER ATTENTION INSPECTION RESULT - OK Green Yellow Red Front / Rear Brake Linings Head Lights/ Tail Lights/ Turn Signals/ Brake Lights/ Hazard Lights/ LF RF Exterior Lamps Windsheild Washer Spray, Wiper Operation, and Wiper Blade Green Green Yellow V Yellow Windsheild Condition (Inspect for Chips, Cracks, or Pitting) Red Radiator, heater and air conditioning hoses for leaks and damage RR LR **Engine Air Filter Condition** Green Green Cabin Air Filter Condition Yellow V Yellow Red Upholstery / Carpet/ Floor Mats / Mirrors / Glass Red Exhaust system (leaks, damage, loose parts) Inspection Not Taken Serviced Steering and steering linkage Boots, Ball Joints, and Dust Covers. 7/32 or greater Fluid Level and Fluid Condition 6/32 to 4/32 Shocks/struts and other suspension components for leaks and/or 3/32 or less damage Check Tires / Tread Depth Drive Belts (Condition and Adjustment) LF Brake System (Lines, Hoses, Parking Brake Cable) Green V Green Drive Shaft Boots / Constant Velocity Boots/ U-Joints/ Transmission Yellow Yellow Linkage (if equiped) Red Red AC and Heating System Operartion RRI RR LR LRI Clutch operation (if equipped) Green Green Engine Oil and/or Fluid Leaks. Yellow Yellow Transmission / Differential/ Transfer Case Check Fluid Level/ Fluid Condition/ Fluid Leaks Spare: Green Yellow Shock Absorbers and Suspension ✓ Serviced Tire Wear and Alignment 7/32 or greater Fuel Lines And Connections/ Fuel Tank Band / Fuel Vapor Vent 6/32 to 4/32 System Inspect Nuts and Bolts on Body Chassis 3/32 or less Check Battery 1 Performance **Engine Mounts Condition** ✓ Good Horn Operation Fair State Inspection and/or Emission Test Due Bad Warning Lights Actual Cold Cranking Amps Engine Oil Level/Condition Factory Cold Cranking Amps Coolant Level/Condition Check Battery 2 Performance V Brake Fluid Level/Condition Good General Maintainence Fair Bad Actual Cold Cranking Amps

Factory Cold Cranking Amps