



# Vehicle History Report™

US \$39.99

## 2020 MERCEDES-BENZ SPRINTER 2500

VIN: W1X4EBHY8LT022811  
CHASSIS AND CAB  
3.0L V6 F DOHC 24V  
DIESEL  
REAR WHEEL DRIVE



No accidents or damage reported to CARFAX



CARFAX 1-Owner vehicle



At least 1 open recall



4 Service history records



Personal vehicle









**3,847** Last reported odometer reading












This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/23/22 at 12:56:47 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


 <b>Ownership History</b> The number of owners is estimated	 Owner 1
Year purchased	2020
Type of owner	Personal
Estimated length of ownership	1 yr. 3 mo.
Owned in the following states/provinces	Utah
Estimated miles driven per year	---
Last reported odometer reading	3,847

 <b>Title History</b> CARFAX guarantees the information in this section	  Owner 1
Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	 <b>Guaranteed</b> No Problem
Not Actual Mileage   Exceeds Mechanical Limits	 <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. <a href="#">Register</a>   <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	 Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	 No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	 No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	 No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	 No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	 No Issues Reported
<b>Manufacturer Recall</b>	Recall Reported

At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.

**Basic Warranty**  
[Original warranty](#) estimated to have 0 months remaining.

 **Warranty Active**










## Detailed History

### Owner 1

Purchased: 2020

Personal Vehicle

Date	Mileage	Source	Comments
07/15/2020 ^		Mercedes-Benz of Stockton Stockton, CA 209-944-5511 berberianmotors.com ★ ^ 4.5^ /^ 5.0 <a href="#">130 Verified Reviews</a> ✓ ♥ ^ 2,529 Customer Favorites	Vehicle sold
07/24/2020 ^ 	9 ^	Alfano Motorcars, Inc. San Luis Obispo, CA 805-543-5752 alfanomotorcars.com/ ★ ^ 4.6^ /^ 5.0 <a href="#">63 Verified Reviews</a> ✓ ♥ ^ 86 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
09/19/2020 ^ 		Crowser Tire & Service Fort Worth, TX 817-625-8473 ★ ^ 5.0^ /^ 5.0 <a href="#">44 Verified Reviews</a> ✓ ♥ ^ 49 Customer Favorites	 Vehicle serviced
11/03/2020 ^	15 ^	Utah Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal vehicle
03/01/2021 ^		Utah Motor Vehicle Dept. Saint George, UT Title #UT007013869	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Passed safety inspection - Vehicle color noted as Silver
 <div style="border: 1px solid gray; padding: 10px; display: inline-block; margin-left: 20px;"> <p>Avoid financial headaches. Make sure the loan has been paid off if you're buying from a private seller. <a href="#">Learn More</a></p> </div>			
03/10/2021 ^ 	2,912 ^	Mercedes-Benz Of St. George Saint George, UT 435-634-7500 mbstgeorge.com/ ★ ^ 4.7^ /^ 5.0 <a href="#">50 Verified Reviews</a> ✓ ♥ ^ 2,249 Customer Favorites	 Vehicle serviced - Maintenance inspection completed
05/27/2021 ^	3,847 ^	Mercedes-Benz Of St. George	Vehicle serviced



Saint George, UT  
435-634-7500  
mbstgeorge.com/

★ 4.7 / 5.0

50 Verified Reviews ✓

♥ 2,249

Customer  
Favorites



- Maintenance inspection completed

06/04/2021  
Å

Mercedes-Benz USA LLC

**Manufacturer Safety recall issued**

- NHTSA #21V152  
- Recall #2021050005  
- Status: Remedy Available

[Click here](#) or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

- [Learn more about this recall](#)

**Description:** Mercedes-Benz AG (MBAG) the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain platform 907 (VS30) Sprinter vehicles, the retaining washer on the bolt that connects the brake pedal to its bearing block could come loose. If the retaining washer comes loose, over time it could detach from the bolt, and in the worst case and with ongoing use of the brake pedal, the bolt may work its way out of the bearing block on one side. If this occurs, the brake lamp switch may become permanently activated even when the brake pedal is not pressed. If the brake lamps are permanently illuminated, it would not be possible for following traffic to determine the braking intention of the vehicle, which could increase the risk of a crash. DVUSA will conduct a voluntary recall campaign. Authorized Mercedes-Benz or Freightliner customers affected by this measure will be informed about the recall and the necessary next steps in writing and will receive notice through the interim customer notification.

If this occurs, the brake lamp switch may become permanently activated even when the brake pedal is not pressed. If the brake lamps are permanently illuminated, it would not be possible for following traffic to determine the braking intention of the vehicle, which could increase the risk of a crash.

**Remedy:** DVUSA will conduct a voluntary recall campaign. Authorized Mercedes-Benz or Freightliner customers affected by this measure will be informed about the recall and the necessary next steps in writing and will receive notice through the interim customer notification.

07/28/2021  
Å

Mercedes-Benz USA LLC

**Manufacturer Safety recall issued**

- NHTSA #21V411  
- Recall #2021070023  
- Status: Remedy Available

[Click here](#) or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

- [Learn more about this recall](#)

**Description:** Mercedes-Benz AG (MBAG) has determined that the software of the MBUX multimedia system might not meet specifications. Under very specific conditions, the MBUX multimedia system might not start and the display might remain black, or could reboot unintentionally after 50 seconds of initial startup. The rearview camera image might not be displayed or the display might be interrupted which could increase a risk of a crash or injury. An authorized dealer will update the MBUX software on the affected vehicles.

The rearview camera image might not be displayed or the display might be interrupted which could increase a risk of a crash or injury.

**Remedy:** An authorized dealer will update the MBUX software on the affected vehicles.

01/26/2022  
Å

Mercedes-Benz USA LLC

**Manufacturer Safety recall issued**

- NHTSA #21V972  
- Recall #2022010005  
- Status: Remedy Available

[Click here](#) or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

- [Learn more about this recall](#)

**Description:** Mercedes-Benz AG(MBAG), the manufacturer of Mercedes-Benz Sprinter Vans was notified of customer complaints claiming a van had "rolled away" after the driver had selected gear position "P" (Park) and P was displayed in the instrument cluster. If the driver does not properly secure the vehicle in accordance with parking instructions in the Operator s Manual, it is possible that the vehicle could roll from its parked position and therefore increase the risk of a crash. An authorized Mercedes-Benz Sprinter dealer will update the ESP control unit with a revised parameter set on the affected vans.

If the driver does not properly secure the vehicle in accordance with parking instructions in the Operator s Manual, it is possible that the vehicle could roll from its parked position and therefore increase the risk of a crash.

**Remedy:** An authorized Mercedes-Benz Sprinter dealer will update the ESP control unit with a revised parameter set on the affected vans.



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

Â© 2022 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.  
2/23/22 12:56:47 PM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2020 MERCEDES-BENZ SPRINTER vehicle (VIN: W1X4EBHY8LT022811), which is based on information supplied to CARFAX and available as of 2/23/22 at 1:56 PM (EST).

Customer Signature

Date

Dealer Signature

Date